

TABLES

| | | |
|-------------|---|------|
| Table 2.1. | Number and Type of Household Units in Thornton Creek Watershed (1998) | 2-9 |
| Table 2.2. | Traffic Counts..... | 2-14 |
| Table 3.1. | Average Monthly Precipitation by Season (Inches) | 3-4 |
| Table 3.2. | Flow Monitoring Locations on Thornton Creek..... | 3-11 |
| Table 3.3. | Estimates of Flows (HSPF Modeling Results) | 3-14 |
| Table 3.4. | Flood-Prone Areas in Thornton Creek Watershed Since 1995 | 3-17 |
| Table 3.5. | Water Rights to Thornton Creek and Its Tributaries..... | 3-19 |
| Table 3.6. | Thornton Creek Sub-basins | 3-24 |
| Table 3.7. | Current Land Uses in Thornton Creek Watershed..... | 3-25 |
| Table 3.8. | Comparison of Land Use by Major Sub-basin | 3-26 |
| Table 3.9. | Active Use Parks (Ball Fields, Playgrounds, Beaches)..... | 3-33 |
| Table 3.10. | Passive Use Parks (Wildlife Parks and Natural Areas)..... | 3-34 |
| Table 3.11. | Land Use by Sub-basin (Acres) | 3-37 |
| Table 3.12. | Impervious Surface Ratings for Various Land Uses..... | 3-38 |
| Table 3.13. | Amounts of Impervious Surface in Thornton Creek Watershed (by Land Use) | 3-38 |
| Table 4.1. | Wetlands in Thornton Creek Watershed (from South to North)..... | 4-8 |
| Table 4.2. | Results of June 1998 Electroshocking | 4-17 |
| Table 4.3. | Assessment Criteria and Measurements for Habitat Survey..... | 4-20 |
| Table 5.1. | Washington State Freshwater Standards for Class AA Streams..... | 5-2 |
| Table 5.2. | King County and Seattle Sample Stations..... | 5-6 |
| Table 5.3. | Summary of Base Flow Water Quality Data for Thornton Creek, 1985 to 1997 (Main Branch)..... | 5-12 |
| Table 5.4. | Summary of Base Flow Water Quality Data for Thornton Creek, 1974 to 1982 (South Branch) | 5-13 |
| Table 5.5. | Summary of Base Flow Water Quality Data for Thornton Creek, 1974 to 1982 (North Branch) | 5-13 |
| Table 5.6. | SPU Summer 1998 Sample Data | 5-14 |
| Table 5.7. | Pesticides Detected in Thornton Creek Stormwater Samples, USGS 1998..... | 5-16 |
| Table 5.8. | Summary of Storm Flow Water Quality Data for Thornton Creek (Main Branch) | 5-17 |
| Table 5.9. | Summary of Storm Flow Water Quality Data for Thornton Creek (South Branch) | 5-18 |
| Table 5.10. | Summary of Storm Flow Water Quality Data for Thornton Creek (North Branch) | 5-18 |
| Table 5.11. | Comparison of Dry-Weather Water Quality in Thornton Creek and King County Creeks..... | 5-19 |
| Table 5.12. | Thornton Creek Project Sampling Sites..... | 5-21 |
| Table 5.13. | Thornton Creek Project Data, Physical Parameters | 5-22 |
| Table 5.14. | Metal Concentrations Detected in Thornton Creek Sediments..... | 5-24 |
| Table 5.15. | Organochlorine Compounds Detected in Thornton Creek Sediments | 5-25 |
| Table 5.16. | Poly-aromatic Hydrocarbon Concentrations Detected in Thornton Creek Sediments..... | 5-25 |
| Table 5.17. | PCBs and Organochlorine Pesticides Detected in Thornton Creek Fish Tissues | 5-26 |
| Table 5.18. | B-IBI Scores for Thornton Creek Benthic Macro-invertebrate Samples..... | 5-27 |
| Table 6.1. | Comparison of Seattle and Shoreline Drainage-Related Building Codes | 6-31 |
| Table 8.1. | Summary of Recommended Drainage Policy Improvement Actions | 8-2 |
| Table 8.2. | Drainage System Components and Routine Maintenance..... | 8-11 |

THORNTON CREEK WATERSHED CHARACTERIZATION REPORT

| | |
|--|-------|
| Table 8.3. Seattle Drainage Capital Improvement Proposed Projects and Budgets..... | 8-17 |
| Table 8.4. Shoreline Drainage Capital Improvement Projects and Budgets | 8-19 |
| Table 10.1. Proposed 1999 Instream CIP Projects..... | 10-21 |
| Table 12.1. Potential Benefits Provided by Thornton Creek and Its Watershed..... | 12-2 |

FIGURES

| | |
|---|------|
| Figure 1.1. Thornton Creek Watershed (1999)..... | 1-3 |
| Figure 1.2. Thornton Creek Watershed (1908)..... | 1-9 |
| Figure 1.3. Northgate Mall Vicinity (1936) | 1-10 |
| Figure 1.4. Northgate Mall Vicinity (1946) | 1-11 |
| Figure 1.5. Northgate Mall Vicinity (1960) | 1-12 |
| Figure 2.1. McKees Accurate Road Map of Seattle and Vicinity (1894) | 2-4 |
| Figure 2.2. Thornton Creek Watershed Population Estimates 1920 – 2010 | 2-8 |
| Figure 2.3. Thornton Creek Neighborhoods..... | 2-10 |
| Figure 2.4. Population Density in Thornton Creek Watershed..... | 2-11 |
| Figure 2.5. Seattle Age Distribution 1990 - 2010 | 2-12 |
| Figure 2.6. Perceptions of Thornton Creek..... | 2-17 |
| Figure 2.7. Reasons to Restore Thornton Creek | 2-18 |
| Figure 3.1. Topography of Thornton Creek Watershed | 3-2 |
| Figure 3.2. The Water Cycle | 3-3 |
| Figure 3.3. Annual Rainfall in Thornton Creek Watershed (inches)..... | 3-4 |
| Figure 3.4. Soil Types in Thornton Creek Watershed | 3-6 |
| Figure 3.5. Geological Features Contributing to Landslide Hazards | 3-8 |
| Figure 3.6. Steep Slopes and Landslide Areas | 3-9 |
| Figure 3.7. Creek Flow Monitoring Stations..... | 3-10 |
| Figure 3.8. Average Flows in Thornton Creek..... | 3-12 |
| Figure 3.9. Flood-Prone Areas in Thornton Creek Watershed | 3-15 |
| Figure 3.10. Surface Water Drainage Incidents in Shoreline | 3-16 |
| Figure 3.11. North, South, and Main Branches and their Drainage Areas | 3-20 |
| Figure 3.12. Thornton Creek Sub-basin Boundaries | 3-23 |
| Figure 3.13. Land Use Distribution in Thornton Creek Watershed..... | 3-25 |
| Figure 3.14. Existing Land Use | 3-27 |
| Figure 3.15. Existing Zoning | 3-29 |
| Figure 3.16. Parks..... | 3-32 |
| Figure 3.17. Schools and Utilities..... | 3-35 |
| Figure 3.18. Percentage of Impervious Surface..... | 3-39 |
| Figure 4.1. Wetlands | 4-7 |
| Figure 4.2. Coho, Chinook, Steelhead, and Cutthroat Trout..... | 4-12 |
| Figure 4.3. Common Freshwater Invertebrates..... | 4-18 |
| Figure 4.4. Instream Physical Characteristics..... | 4-21 |
| Figure 4.5. Water Typing | 4-25 |

| | |
|--|-------|
| Figure 4.6. Creek, Pipes, and Ponds near I-5 and Northgate Mall | 4-41 |
| Figure 5.1. King County, Seattle, and USGS Sample Stations | 5-7 |
| Figure 5.2. Fecal Coliform Levels in Thornton Creek Samples | 5-9 |
| Figure 5.3. Benthic Macro-invertebrate Sampling Sites..... | 5-28 |
| Figure 8.1. Storm Drains, Ditches and Culverts in Thornton Creek Watershed (Seattle Portion) | 8-5 |
| Figure 8.2. Publicly Owned Detention Ponds in Thornton Creek Watershed..... | 8-8 |
| Figure 8.3. Illustration of Some Drainage System Components..... | 8-10 |
| Figure 8.4. Drainage Capital Improvement Projects in Thornton Creek Watershed (Seattle and Shoreline)..... | 8-16 |
| Figure 10.1. Habitat Survey of Thornton Creek Park #1 (1995) | 10-3 |
| Figure 10.2. Habitat Survey of Thornton Creek Park #6 (1995) | 10-3 |
| Figure 10.3. Open Space Acquisition Sites..... | 10-8 |
| Figure 10.4. Community Restoration Projects | 10-15 |
| Figure 10.5. Habitat-related Capital Improvement Projects..... | 10-19 |